


(Athens) Dawson ec. #2



Sec. 8
T. 16 N.
R. 3 E.
W. W.
Index No.



Mine originally operated by: (1)

Wabash Coal Co. #2
Dawson.

Date 1883.

Original name or number:

Illinois Coal Report

p.

LATER OPERATORS

Date

Operator

Name or No.

2	1914	Abd'd.	
3	reopened	1917	
4		J. D. 1956	- 1917 coal apt.
5	:		
6			
7			
8			
9			
10			
11			
12			
13			
14			

See map in Rpt.
1884 coal apt.
J.D., 1956

* Also owners

See ownership sheet

Railroad, Wagon, Idle, Abandoned

IDENTIFICATION

County No.

Coal No.




Part

Quad.

County

Sangamon.



Sec.

T.

R.

Index No.

~~36~~ 8
~~18~~ N 16
~~6~~ W. 3

COAL MINE OPERATOR



Mine originally operated by: (1)

Date

1917

Athens Dawson C. Co.
Dawson.

Original name or number:

Illinois Coal Report

p.

LATER OPERATORS

Date

Operator

Name or No.

2

3

4

5

6

7

8

9

10

11

12

13

14



Map next page.

* Also owners

See ownership sheet

Railroad, Wagon, Idle, Abandoned

SHIPPING MINE -

IDENTIFICATION

County No.

Coal No.




Part

Quad. 174.

County

Sangamon.



Sec. 8


T. 16 N.


R. 3 E. W.

Index No.

1108

COAL MINE OPERATOR





T16N R3W

Map.
Date 5-27-19

Operator

Name or No.

County Sangamon

Athens-Dawson C. Co
Index No. 1108

Location and Elevation Data

Location: Exact ~~Approximate~~

(Approximate only if no trace or record of original exists)

Location by W. B. RoeDate 5-5-31 Notebook No. 602 Page 41-393

Looseleaf ref. _____

Map files No. 12-83-14

Description of location


Position in sec., $\frac{1}{4}$ sec., 40 acres

_____ feet from North line

_____ feet from East line

_____ feet from South line

_____ feet from West line

Sec. 8T. 16 N.R. 3 W.

Farm _____

No. _____

Company _____

Dawson C. & M. Co.

No. _____

County No. _____

Other description: _____

Elevation 599.2 ft.By W. B. Roe

Method: Level, transit, alidade, hand level

AlidadeElevation of Top foundation of tibble

Height of point above ground _____

Date 5-5-31 Notebook 602 P. 41-393

Looseleaf ref. _____

Map files No. 12-83-14Description of item: (drill hole, mine, etc.) Mine shaft.

SHIPPING MINE

County Duganow Quadrangle _____Index No. 1108

TOWN *Dawson* 6 N R. 3 W S. 8 NW 1/4 NW 1/4 Sangamon CO.COAL BED *5*

DATE

COLLECTOR

1888

OPERATOR *Wabash coal Co.,*MINE *Dawson #1*HEAD OFFICE *Quincy, Illinois.*

CAPACITY

MARKETS, FRT.

*El same as station at Dawson.*ENTRANCE *Shaft (250) (240)*

CAGE

ENGINES

597

DRUM

*250**347*

SCREENS

STORAGE

VENTILATION

GAS, SOURCE

COAL THICKNESS, AV. *62"* MAX. MIN. ELE. *Wabash R.R 600. 350 Ab. Sea FT.*SECTION LOCATED *Face 3rd N off 1st W. off 1st south.*

No.		In.	No.		In.
1	<i>Coal</i>	<i>54</i>	7		
2			8		
3			9		
4			10		
5			11		
6				TAPE	

NOT SHIPPED

NOT INCLUDED

CAN

SAMPLE

PHYSICAL PROPERTIES BY NOS.

ROOF *Black slate 2' to 3', ss. cap rock 1/2' to 6', Very good roof.*FLOOR *Fire clay.*

DIP

CLEAT

FAULTS, ETC.

MACHINES

HAULAGE

DRAINAGE

WORKING SYSTEM

ENTRIES, MAIN

CROSS

PILLARS, MAIN

CROSS

DRAWN

TIMBERS

*Wrong location for #1 or #2
either mine see map in Coal report. J.D., 1956*

Note also: Variation in coal, impurities, roof, structure.

Collect records, analyses, fossils. Note land values, etc.

Correspondence. *Moses. N 15, P 20 (Savage NB-12 p 94)*